


Not
Approved
JB
2-7-05



Best Available Copy

Replacement Sheet




Fig 2

Replacement Sheet




Fig 3

Replacement Sheet




Fig 4

3



2

This diagram shows a complex mechanical assembly in a perspective view. The assembly includes a central body with various internal and external components. Key features include a central shaft or rod (121) passing through the assembly, a valve or piston mechanism (120, 122, 124) at the bottom, and a series of angled, ribbed structures (116, 118, 120) on the right side. Numerous other parts are labeled with numbers, including 22, 24, 26, 27, 28, 29, 34, 40, 42, 50, 52, 55, 57, 58, 60, 64, 84, 90, 96, 97, 98, 99, 112, 126, and 128. The drawing is a technical illustration of a mechanical device.

Fig 7

Replacement Sheet




Fig 8

Replacement Sheet




Fig 9

Replacement Sheet




Fig 10

Replacement Sheet




Fig 11

Replacement Sheet




Fig 12

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.